



TBF Linen and Prestige Ceiling Warranties and Limitations

LIFETIME (30-YEAR) LIMITED WARRANTY

All Linen and Prestige suspension systems, when used with any TBF ceiling panels carry a lifetime (30-year) warranty that our product shall be free from manufacturing defects and that the suspension systems shall be free from the occurrence of 50% red rust.

TBF ceiling tiles are specially formulated to endure environments with up to humidity 99% relative humidity and temperatures up to 104°F. These panels carry a limited warranty against visible sag for up to 30 years installed in our suspension system.

TBF mineral-fiber ceiling treated with a antimicrobial formulation inhibits and retards the growth of mold/mildew, fungi, yeast and odor/stain causing Gram-positive and Gram-negative bacteria. This formulation is an antimicrobial treatment.

In addition, TBF Superior Performance ceiling panels, TBF cast-mineral-fiber treated with high-performance, broad spectrum antimicrobial formulation have shown superior performance when tested against untreated panels.

TBF Superior Performance ceiling panels tested have achieved a 10 rating. This is the highest rating achievable and signifies "no growth."

TBF Superior Performance ceiling tiles are the only standard ceilings products on the market with a limited lifetime (30 year) warranty against mold and mildew growth, subject to use under normal conditions.

TBF Superior Performance products feature an antimicrobial treatment that provides broad-spectrum control for mold/mildew, fungi, yeast, algae, and bacteria.

When installed in our suspension system, these panels are guaranteed for the lifetime (30 Years) of the product, subject to use under normal conditions, to inhibit or retard microbial growth on product treated surfaces that can result from high humidity conditions.

Continued mold inhibition cannot be assured if ceiling panels and tile with TBF Superior Performance are installed in or exposed to abnormal conditions. Abnormal conditions include chemical fumes, vibrations or moisture coming in direct contact with the ceiling, such as building leaks or condensation.

TBF ceiling tiles are Class A Fire Rated.